Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1845Work Order Type: WeatherizationAudit Name: 14014SO1845

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO1845 FAYETTEVILLE, TN 37334

Alt. Client ID: LINCOLN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name:
Client ID: 14014SO1845
Alt. Client ID: LINCOLN

Work Order (Bid Form)
Work Order Name: 14014SO1845
Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 5

Measure 1 Inf	Infiltration Redctn Components						Inspected	
BEDR	DUCE INFILTRATION BY OOM WINDOW CASE PLACE 2 STORMS	452 CFM'	S - AIR	SEAL ARO	UND BA	CK		
			Estimated A				Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Measure 2 Flo	oor Ins. R-19			Componen				Inspected
Comment				Estimated	1		Actual	
	Description / Comment Floor Insulation - Fiberglass Batts - R-19	<i>Units</i> SqFt	Qty 1032	•		Qty		Inspected
Comment # Material / Labor	Description / Comment Floor Insulation -		Qty	Estimated	1	Qty	Actual	
# Material / Labor 1 Insulation	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt	Qty 1032	Estimated	1	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt	Qty 1032	Estimated	1	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt SqFt	Qty 1032 1032	Estimated	1		Actual	

Report Run On: 5/28/2010

Measure 3 Wa	II Insulation			Componen	ts			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
I Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1013					
2 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1013					
Other Detail				1		1	1	
L								
			Measure	Sub Total:] ;	Sub Total:	
Comment 1. INS 2. W/S	ic Ins. R-30 / R-19 FALL NEW PULL DOWN V ACCESS ISE PACK UNDER FLOOR		TCH	Componen	ts			Inspected
Comment 1. INS 2. W/S	TALL NEW PULL DOWN V		TCH	Componen Estimated			Actual	Inspected
Comment 1. INS ⁻ 2. W/S 3. DEN	TALL NEW PULL DOWN V		TCH			Qty		Inspected
Comment 1. INS 2. W/S	TALL NEW PULL DOWN V ACCESS ISE PACK UNDER FLOOI	RED ARE	TCH EA	Estimated	<u> </u>	Qty	Actual	
Comment 1. INS 2. W/S 3. DEN Material / Labor Insulation	TALL NEW PULL DOWN NACCESS ISE PACK UNDER FLOOP Description / Comment Attic Insulation - Blown	RED ARE	TCH A Qty	Estimated	<u> </u>	Qty	Actual	
Comment 1. INS 2. W/S 3. DEN 3. DEN Insulation	FALL NEW PULL DOWN NACCESS ISE PACK UNDER FLOOP Pescription / Comment Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown	RED ARE <i>Units</i> SqFt	TCH EA Qty 480	Estimated	<u> </u>	Qty	Actual	
Comment 1. INS 2. W/S 3. DEN 3. DEN 4 Material / Labor 1. Insulation 2. Labor 3. Insulation 3. Insulation	FALL NEW PULL DOWN NACCESS ISE PACK UNDER FLOOP Pescription / Comment Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown	RED ARE Units SqFt SqFt	TCH EA Qty 480 480	Estimated	<u> </u>	Qty	Actual	
Comment 1. INS 2. W/S 3. DEN 3. DEN 4 Material / Labor 1 Insulation 2 Labor 1 Insulation 3 Insulation	FALL NEW PULL DOWN NACCESS ISE PACK UNDER FLOOR Description / Comment Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	Wnits SqFt SqFt SqFt	TCH EA Qty 480 480 552	Estimated	<u> </u>	Qty	Actual	
Comment 1. INS 2. W/S 3. DEN 3. DEN 4 Material / Labor 1 Insulation 2 Labor 1 Insulation 4 Labor 1 Labor 1 Labor 1 Insulation 1 Labor 1 Insulation 1 Labor 1 L	FALL NEW PULL DOWN NACCESS ISE PACK UNDER FLOOR Description / Comment Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	Wnits SqFt SqFt SqFt	TCH EA Qty 480 480 552	Estimated	<u> </u>	Qty	Actual	
Comment 1. INS 2. W/S 3. DEN 3. DEN 4 Material / Labor 1 Insulation 2 Labor 1 Insulation 4 Labor 1 Labor 1 Labor 1 Insulation 1 Labor 1 Insulation 1 Labor 1 L	FALL NEW PULL DOWN NACCESS ISE PACK UNDER FLOOR Description / Comment Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-19 Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	Wnits SqFt SqFt SqFt	TCH EA Qty 480 480 552	Estimated	<u> </u>	Qty	Actual	

Report Run On: 5/28/2010

Measure 5 Fix I Comment	mproper Venting (Clothe	es Dryer)	Componen	ts		,	Inspecte	
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Health and Safety Items	Metal Flex	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
			Measur	e Sub Total:		;	Sub Total:		
Measure 6 Smo	oke Detector is Needed			Componen				Inspecte	
		Units	Qty	Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspecte Total	
Comment	Description / Comment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual		
Comment # Material / Labor 1 Health and Safety	Description / Comment			Estimated	1	Qty	Actual		
Comment # Material / Labor 1 Health and Safety Items	Description / Comment Smoke / Carbon detector	Each	1	Estimated	1	Qty	Actual		
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Smoke / Carbon detector	Each	1	Estimated	1	Qty	Actual		
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Smoke / Carbon detector	Each	1	Estimated	1		Actual		

Report Run On: 5/28/2010

	oor Barrier Needed sement/Crawlspace)			Componen	ts		ı	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	